



652 Oliver Street  
Williamsport, PA 17701 U.S.A.  
Tel. 570-323-6181  
Fax. 570-327-7101  
www.lycoming.textron.com

# MANDATORY SERVICE BULLETIN

January 20, 2003

Supplement No. 2  
(Supersedes Supplement No. 1 to Service Bulletin No. 555)

To  
Service Bulletin No. 555

On page 1 of 8 of Service Bulletin No. 555, "Oil Pump Body Plug Inspection", dated November 25, 2002, steps 1, 2 and 3 under the Note in Models Affected should read as follows:

1. P/N **78528** shipped between 5/1/01 and **the date of this supplement.**
2. P/N 78890 shipped between 9/17/01 and **the date of this supplement.**
3. P/N 51A22618 shipped between 9/29/00 and **the date of this supplement.**