



A Textron Company

652 Oliver Street
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181
Fax. 570-327-7101
www.lycoming.textron.com

SERVICE INSTRUCTION

March 21, 2002

Supplement No. 1

To

Service Instruction No. 1070M

On page 2 of Service Instruction No. 1070M, in the TABLE OF SPECIFIED FUELS, the third row of Engine Models has an incorrect prefix. The engine model listed in bold below denotes the correct prefix.

O-320-B, -D; IO-320-B, -D; LIO-320-B1A; AEIO-320-D; AIO-320-A, -B, -C; O-480-A; O-360-A, -C; IO-360-B, -E, -L, -M; AEIO-360-B, -H; VO-360-A, -B; IVO-360-A; HO-360-A, -B, -C; HIO-360-B; O-435-A2; GO-435-C2*; O-540-A, -D, -E, -F, -G, -H; IO-540-C , -D, -E, -N, -T; AEIO-540-D	91/96	100LL or 100	91/96UL or ④B91/115 or ④91 or ④100/130 or ④115/145
--	-------	----------------------------	--