


- [Home](#)
- [Aviation safety](#)
- [Database](#)
- [Investigation](#)
- [News](#)
- [Photos](#)
- [Statistics](#)
- [Contact us](#)
- [About](#)

[Home](#) » [ASN Aviation Safety WikiBase](#)

ASN Wikibase Occurrence # 212402

Last updated: 16 January 2019

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can [submit corrected information](#).

Date: 20-JUN-2018
Time: evening
Type: Jodel D.9 Bebe
Owner/operator: Private
Registration: 26PF/F-JUNS
C/n / msn:
Fatalities: Fatalities: 1 / Occupants: 1
Other fatalities: 0
Aircraft damage: Written off (damaged beyond repair)
Location: Mosbach -  [Germany](#)
Phase: Take off
Nature: Private
Departure airport: Mosbach-Lohrbach airfield
Destination airport:

Narrative:

The plane failed to take off and crashed in a field next to the runway. The pilot died in the crash.

Sources:

<https://www.tag24.de/nachrichten/mosbach-lohrbach-unfall-crash-unglueck-flugzeug-absturz-pilot-tot-toter-polizei-ursache-ermittlungen-650804>

www.arcor.de

Tower

<https://www.mz-web.de/panorama/unglueck-bei-mosbach-38-jaehriger-pilot-stirbt-bei-absturz-von-kleinflugzeug-30658798>

Images:



14.11.2014 W.Lübbers

Revision history:

Date/time	Contributor	Updates
21-Jun-2018 08:00	gerard57	Added
21-Jun-2018 08:28	gerard57	Updated [Aircraft type, Source]
21-Jun-2018 11:34	copi	Updated [Aircraft type, Registration, Source, Photo,]
21-Jun-2018 21:51	Iceman 29	Updated [Time, Source, Embed code]

Corrections or additions? ... [Edit this accident description](#)

- [Home](#)
- [Disclaimer](#)
- [Copyright](#)
- [Privacy](#)
- [Submit correction](#)

• Unless otherwise stated: copyright © 1996-2019 Aviation Safety Network
(ASN)